




VERTICAL CLEARANCE DEFICIENCIES



Tag #	PM	Location Description
1	18.15	Main Street OC
2	18.02	E26-N99 Connector OC
3	17.46	Golden Gate Ave OC
4	17.39	East Stockton UP
5	17.22	Route 4/99 Separation
6	16.87	Route 4 Connector
7	16.70	Mariposa Road Separation
8	14.61	Arch Road OC
9	8.83	North Manteca OC
10	7.93	Louise Ave OC
11	7.46	Cottage Ave OC
12	4.89	Austin Road OC
13	0.89	Main Street OC

Disclaimer Statement:
This is not a proposal

This is a display of vertical clearance deficiencies for bridge structures if strict Interstate standards were applied.
Future negotiations with the U.S. Department of Transportation may eliminate some or all of the listed locations.

